

FOCTT2 Firmware Update Tool for macOS v1.0.9

Contents

- General 2
 - Supported Hardware..... 2
 - Supported OS Compatibility 2
 - Tested OS Compatibility 2
 - Released Production Files..... 2
 - Product Upgrade 2
- New Features 3
 - New Features added in version 1.0.9 3
- Resolved Issues 4
 - Issues resolved by version 1.0.9 4
- Outstanding Issues..... 5
 - New Issues 5
 - Existing Issues..... 5
- Document History 6

Copyright © 2020 Panduit Corp. All rights reserved. No part of this book shall be reproduced, stored in a retrieval system, or transmitted by any means, electronic, mechanical, photocopying, recording or otherwise, without written permission from Panduit. No patent liability is assumed with respect to the use of the information contained herein.

Although every precaution has been taken in the preparation of this book, Panduit assumes no responsibility for errors or omissions. Neither is any liability assumed for damages resulting from the use of the information contained herein.

General

V1.0.9 is a GENERAL RELEASE of the OCTT2 Firmware Update Tool.

Supported Hardware

<i>Model</i>	<i>Required Firmware to support Release</i>	<i>Notes</i>
OCTT2	Boot loader v2.03 and newer Firmware v1.0.3 and newer	FOCTT2_FWUP_Mac v1.0.9 includes firmware v1.1.1.

Supported OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X 10.9.5 and newer	Yes	We expect this software to work correctly on all versions of MacOS X 10.9.5 or newer. If you encounter an issue, please see "Troubleshooting: Support."

Tested OS Compatibility

<i>Application</i>	<i>Support</i>	<i>Known Limitations</i>
Mac OS X Mavericks	v10.9.5	
macOS El Capitan	v10.11.5	
macOS High Sierra	v10.13.4	

Released Production Files

Product Upgrade

Image Information

Filename: FOCTT2_FWUP_Mac_1_0_9.dmg
 Filesize: 4405299 bytes
 CRC32: F0DA0791
 MD5: 92780b860226556d0b3e661a26da88d2
 SHA1: 1f76f99bf379922c5e6e6bead7ab73d36a0bf8ef
 SHA256: a77c2f2994e9812b5593bf6a11548ba0a977aca14ba691691313047458c1f62a
 SHA512:
 8510b6d0f51f9a2f60ea1c06919ce88cadfb55e48f7e320004f96dedc1dca0f9ed25464b4d1c0
 58e31630bd36e0a69f501414779ab3553d2090f2c145f744bda
 RIPEMD160: 2b2f23da86acb3b8f575495f57a85fb2ae90993a

New Features

New Features added in version 1.0.9

<i>Issue ID</i>	<i>Title</i>
OC-306	The firmware loader provides firmware v1.1.1.

Resolved Issues

Issues resolved by version 1.0.9

<i>Issue ID</i>	<i>Title</i>
	N/A

Outstanding Issues

New Issues

The following reported problems have been found since the previous release and are still outstanding in this release.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
	N/A		

Existing Issues

The following reported problems were found prior to the previous release and are still outstanding.

<i>Issue ID</i>	<i>Title</i>	<i>Version</i>	<i>Status</i>
OCBgz115	When updating a tool from 1.0.3 to 1.0.6, the word "Complete" did not propagate correctly.	BL2.03	Fixed in BL2.04

OCBgz115 Sometimes the status reported by Bootloader v2.03 is not accurate when the firmware update has failed or when it has completed successfully.

Workaround: If other USB devices are attached to the computer, remove them. If no other USB devices are attached to the computer, then attach another USB device, or plug the OptiCam2 into a different USB port, or plug the OptiCam2 into a USB hub. Retry the firmware update procedure until the OptiCam2 LCD screen shows the updated firmware version at the top of the "... "Select Option" screen.

Document History

Revision	Date	Reason for Change
1	Nov 3, 2020	Include firmware 1.1.1.