VeriSafe[™] Insulation Piercing Connector



applications

The VeriSafe™ Insulation Piercing Connector provides a fast, secure, and reliable way to terminate AVT sensor leads. The compact connector design accommodates up to two taps in a single housing that fully insulates both connections. The patent pending connector allows taps to be made without compromising the integrity of conductors and includes integrated strain relief. Installation is fast and easy without the need to strip conductors. Ideal for new and retrofit applications, connections can be made without modifying existing conductor runs.





specifications

Insulation piercing connector for copper wire with two mechanically isolated taps. Optimized for use with VeriSafe™ AVT sensor leads when prepared with Panduit ferrules, P/N F80-12-M.

technical information

Cable run:	14 – 3/0 AWG (Copper conductors, solid or stranded Class B & C)
Taps:	(2) 14 AWG stranded Class K
	For VeriSafe AVT sensor leads prepared with F80-12-M ferrules
Connector materials:	Housing – polyamide
	Insulator – elastomeric polymer
Operating temperature:	Up to 90°C (194°F)
Voltage range:	600V maximum
Standards & compliance:	UL 486A-UL 486B, CSA C22.2 No 65-13
	cULus listed
	RoHS compliant

key features and benefits

Compact and space saving:	Terminate two taps with a single connector
	Fewer parts, less space needed for each installation
	Optimized for use with VeriSafe [™] Absence of Voltage Tester sensor leads
Fast installation:	Insulation piercing design allows for installation without the need to strip insulation from conductors
	Easily retrofit existing cable runs without modifying conductors
Fully insulated design:	Safe and reliable connections
Secure connections:	Taps are made without compromising the integrity of conductors
	Housing includes integrated strain relief
Flexible design:	Family of connectors covers a wide range of cable runs
	Suitable for new or retrofit applications



Insulation Piercing Connectors

VS-CKP14-6:

VeriSafe[™] Insulation Piercing Connection Kit for Tapping 14 to 6 AWG conductors. Kit includes

3 connectors for installment of 1 AVT.

VS-CKP4-000:

VeriSafe[™] Insulation Piercing Connection Kit for Tapping 4 to 3/0 AWG conductors. Kit includes 3 connectors for installment of 1 AVT.

Equipment Retrofit Kits

VS-AVT-RKP1: Complete kit to retrofit equipment with VeriSafe™ Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, VeriSafe[™] Insulation Piercing Connection Kit 14-6 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.


VS-AVT-RKP2:

Complete kit to retrofit equipment with VeriSafe™ Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, VeriSafe™ Insulation Piercing Connection Kit 4 - 3/0 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.

VeriSafe[™] Insulation Piercing Connector

part information

Part Number	Product Description
VS-CKP14-6	VeriSafe™ Insulation Piercing Connection Kit for tapping 14 to 6 AWG conductors. Includes 3 connectors and 12 insulated ferrules for 14 AWG stranded Class K wires (VeriSafe AVT sensor leads).
VS-CKP4-000	VeriSafe [™] Insulation Connection Kit for tapping 4 to 3/0 AWG conductors. Includes 3 connectors and 12 insulated ferrules for 14 AWG stranded Class K wires (VeriSafe AVT sensor leads).
VS-AVT-RKP1	Complete kit to retrofit equipment with VeriSafe [™] Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, VeriSafe [™] Insulation Piercing Connection Kit 14-6 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.
VS-AVT-RKP2	Complete kit to retrofit equipment with VeriSafe [™] Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, VeriSafe [™] Insulation Piercing Connection Kit 4 - 3/0 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.



related products

Part Number	Product Description
VS-CKSB10-8	VeriSafe™ Split Bolt Connection Kit for tapping 10 to 8 AWG conductors. For use with VeriSafe™ Absence of Voltage Tester.
VS-CKSB6-2	VeriSafe™ Split Bolt Connection Kit for tapping 6 to 2 AWG conductors. For use with VeriSafe™ Absence of Voltage Tester.
VS-CKSB1-00	VeriSafe™ Split Bolt Connection Kit for tapping 2 to 2/0 AWG conductors. For use with VeriSafe™ Absence of Voltage Tester.
VS-AVT-RKSB1	Complete kit to retrofit equipment with VeriSafe [™] Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, Split Bolt Connection Kit 10-8 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.
VS-AVT-RKSB2	Complete kit to retrofit equipment with VeriSafe [™] Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, Split Bolt Connection Kit 6-2 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.
VS-AVT-RKSB3	Complete kit to retrofit equipment with VeriSafe [™] Absence of Voltage Tester. Includes AVT device with 10ft. sensor leads, 8ft. system cable, Split Bolt Connection Kit 2-2/0 AWG power connectors, (12) cable ties, (6) cable ties mounts, (1) wire marker card.
PVS0507W2103Y	NFPA 70E Arc flash label, 5.0" H x 7.0" W (127.0mm x 177.8mm), warning header, 'Arc flash & shock hazard appropriate PPE required' (legend), vinyl adhesive, orange header and black/white, 1 sign/card, 5 cards/package.
PSL-KT-PWRP	Power and Panel Distribution Lockout Kit







LOTO Stations and Kits



Absence of Voltage Tester Retrofit Kit

WORLDWIDE SUBSIDIARIES AND SALES OFFICES

Phone: 800.777.3300

PANDUIT US/CANADA PANDUIT EUROPE LTD. London, UK Phone: 44.20.8601.7200 PANDUIT SINGAPORE PTE. LTD. Republic of Singapore Phone: 65.6305.7575

PANDUIT JAPAN Tokyo, Japan Phone: 81.3.6863.6000

PANDUIT LATIN AMERICA Guadalajara, Mexico Phone: 52.33.3777.6000

PANDUIT AUSTRALIA PTY. LTD. Victoria, Australia Phone: 61.3.9794.9020



