# Opticom Series 4-to-1 Breakout Fiber Optic Cassettes



#### technical information

The Opticom 4-to-1 Breakout Cassette facilitates the breakout of two MPO-8 to 4 duplex LC connectors. This enables a single parallel-optics switch port (40GBASE-SR4, 100GBASE-SR4, 400GBASE-SR4) to support eight duplex LC-based switches or servers. Opticom Breakout cassettes may also connect to a SAN switch to storage arrays at 8/16/32G speeds. All cassettes are factory terminated and tested to deliver verified optical performance and reliability for quick deployment and improved network integrity.



### applications

Application areas include key elements as specified in Data Center Cabling Standard TIA 942 cross connects in main, horizontal, and equipment distribution areas. Allows for the connection of two MPO-based port to four LC-based components, such as LAN or SAN switches, and servers. Supports 40G to 4×10G, 100G to 4×25G, 400G to 4×100G or 128G to 4×32G.

#### construction

<del>oonotraotro</del>	••								
Fiber count:	16 - 8x LC Duplex connectors and 2x MPO 8 connectors								
Fiber types:	Multimode:	OM4 50/125µm OM4+ 50/125 um OM5 50/125 um							
	SingleMode:	OS2 9/125µm							
Front connectivity:	Multimode with PC Polish								
	Singlemode with UPC Polish								
Split sleeve material (SC or LC adapters):	Zirconia ceramic:	All cassettes							
Rear MTP*	Multimode:	MTP Pinned, PC							
connectivity:	Singlemode:	MTP Pinned, APC							

#### standards

Connectivity meets or exceeds TIA/EIA-568-C.3 performance requirements. Supports IEEE 802.3ba (40/100 Gigabit Ethernet).

environmental properties

Operating temperature:	Room Temperature	0°C to +70°C
		(32°F to 158°F)
Storage and shipping		-40°C to +75°C
temperature:		(-40°F to 167°F)

## performance properties

Insertion loss (Link loss):	Standard Loss (per channel):	•					
	Ultra Loss - MM (per channel): 0.35dB max. Optimized Loss - MM						
	(per channel):	0.5dB max.					
Return loss:	Per channel:	>55dB Singlemode					
		>26dB Multimode					
Connector durability:	Connectors meeting ANSI/TIA-586C.3						
	Durability: 500 ı	mating cycles					

<sup>\*</sup>MTP is a registered trademark of US Conec Ltd.

# **Opticom Series 4-to-1 Breakout Fiber Optic Cassettes**

# part number configurator

FC3ZO-16-10U2 - 40G 10G QuickNet cassette with OM4 fiber, optimized low loss, 16 fiber total, front LC duplex aqua adapter, rear male MTP (pins); Universal pair flipped

Character

Example

1 F

4 Z

5

0

6

8 6

9

10

11 12 0 U 13

1 - Fiber Product

F = Fiber

2 - Product

C = Cassette

3 - Generation

3 = 4-to-1 breakout

4 - Fiber Type

9 = OS2 Singlemode 9/125µm

S = OM4 + 50/125 um

W = OM5 50/125 um

5 - Fiber Performance

N = Standard - OS2 only

O = Optimized U = Ultra

6 - Dash

7 and 8 - Numbers of Fibers

16 = 16-Fiber total

9 - Dash

10 and 11 - Adapter Type


10 = Duplex LC Adapter

12 - Polarity

U = Universal

U2 = Universal (pair flipped)

# QuickNet™ MTP\* Fiber Optic Cassettes





4 to 1 Breakout Cassette Fiber pin-out  Method U (to be used in Breakout Applications)																	
				MP	O #1				MPO #2								
LO Davit Novale an	1 2		2	3		4		1		2		3		4			
LC Port Number	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α	
MPO* Fiber Position	1	12	2	11	3	10	4	9	12	1	11	2	10	3	9	4	

<sup>\*</sup> Key Up/Key Down Adapter (Black Color) - Requires Method B MPO Connectivity

Opticom Method U2 16f Cassette Method U2 (to be used in multi cassette link)																
MPO #1 MPO #2																
LO David November	1 2		2	3		4	4		1		2		3		4	
LC Port Number	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α	В	Α
MPO* Fiber Position	12	1	11	2	10	3	9	4	12	1	11	2	10	3	9	4

Key Up/Key Down Adapter (Black Color) - Requires Method B MPO Connectivity





Dimensions are in inches. [Dimensions in brackets are metric].

**WORLDWIDE SUBSIDIARIES AND SALES OFFICES** 

PANDUIT US/CANADA Phone: 800.777.3300 PANDUIT EUROPE LTD. London, UK Phone: 44.20.8601.7200 PANDUIT SINGAPORE PTE. LTD. Republic of Singapore Phone: 65.6305.7575 PANDUIT JAPAN Tokyo, Japan Phone: 81.3.6863.6000

PANDUIT LATIN AMERICA Guadalajara, Mexico Phone: 52.33.3777.6000 PANDUIT AUSTRALIA PTY. LTD. Victoria, Australia Phone: 61.3.9794.9020

For a copy of Panduit product warranties, log on to www.panduit.com/warranty

For more information

Visit us at www.panduit.com
Contact Customer Service by email: cs@panduit.com
or by phone: 800.777.3300

© 2023 Panduit Corp. ALL RIGHTS RESERVED. FBSP85-WW-ENG 12/2023



<sup>\*</sup>MTP is a registered trademark of US Conec Ltd.